

09768161.012401




Fig. 1




Fig. 2




FIG. 3




Fig. 4




Fig. 5A




Fig. 5B

09768161.012401  
T04210" T9T89260




Fig. 6




Fig. 7




Fig. 8










Fig. 9






Fig. 11

500

0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0

516

Compare

640

x	x	x	0
x	x	63	x
x	191	x	x
0	x	x	x

$T_4 = (0, 63, 191, 0)$   
 $\delta_4 = 32$   
 x = don't care

Subtract

652

x	x	x	0
x	x	0	x
x	93	x	x
0	x	x	x

Absolute Value

654

x	x	x	0
x	x	0	x
x	93	x	x
0	x	x	x

Pass/Fail

656

x	x	x	P
x	x	P	x
x	F	x	x
P	x	x	x

Fig. 12

09768161.012401  
T04210" T9T85260




Fig. 13

09765161.01441  
104210 19189260




Fig. 14

09768161.012401  
FOI-2019-0189260




Fig. 15




Fig. 16






Fig. 17




Fig. 18